

Detecting No Controller

On 9000 series MF and Gleaner combines using a Topcon System 150 auto steer controller - GX45 console and AGI3 antenna. There are occasions where you may not detect Steering Controller - "Detecting Controller" in the steering profile page. One thing to check is the wheel angle sensor (W.A.S.) wiring at the sensor it self. There are times that a broken wire near the sensor will not allow Steering Controller to be detected. This can be verified by disconnecting the sensor harness plug. The wheel angle sensor is located at front of rear axle.

