# Precision Ag - Clearing NVRAM on AGI-4/AGI-3 Receivers from the X30

1. From the setup screen select User.
2. Then select Access Level and log in in dealer mode.

Keywords

AGI-3, AGI-4, System 350

3. Then select System>GPS> Advanced Configuration.
4. From Advanced configuration press the Reset NVRAM button.

Included Images

View the full-size images at the Topcon Totalcare site.